

# High-Resolution Main spindle position encoders

Project Planning Manual

DOK-ENCODR-MAIN\*POSENC-PRJ1-EN-P

*Titel* High-resolution main spindle position encoders

*Type of documentation:* Project Planning Manual

*Documenttype* DOK-ENCODR-MAIN\*POSENC-PRJ1-EN-E1,44

*Internal file reference*

- Mappe 7
- HSP\_E-PJ.pdf
- 209-0042-4119-00

*Reference* This electronic document is based on the hardcopy document with document desig.: 209-0042-4119-00 EN/07.94

*This documentation is used:*

- It lists all the exact order numbers to make ordering easy.
- It assists in integrating the main spindle position encoder into the spindle structure.
- It lists guidelines on installing the high-resolution main spindle position encoder.
- It runs through the checklist of function tests to be run once the encoder is installed.
- It assists in identifying the individual components delivered.

*Change procedures*

Designation of documentation up to present edition	Release-date	Coments
209-0042-4119-00 EN/07.94	Jul./94	First Edition
DOK-ENCODR-MAIN*POSENC-PRJ1-EN-E1,44	Mar./97	First E-Dok

*Copyright* © INDRAMAT GmbH, 1994  
 Copying of this document, and giving it to others and the use or communication of the contents thereof, are forbidden without express authority. Offenders are liable to the payment of damages.  
 All rights are reserved in the event of the grant of a patent or the registration of a utility model or design. (DIN 34-1)

The electronic documentation (E-doc) may be copied as often as needed if such are to be used by the consumer for the purpose intended.

*Validity* All rights reserved with respect to the content of this documentation and the availability of the products.

*Publisher* INDRAMAT GmbH • Bgm.-Dr.-Nebel-Straße 2 • D-97816 Lohr  
 Telefon 0 93 52 / 40-0 • Tx 689421 • Fax 0 93 52 / 40-48 85

Dept ENA (MR, FS)

---

## Table of Contents

<b>1. Applications and features</b>	<b>4</b>
1.1. Applications .....	5
1.2. Components and installation variations .....	7
1.3. Designs .....	10
<b>2. Mechanical data</b>	<b>11</b>
2.1. Dimensional data .....	11
2.2. Technical data .....	19
2.3. Type codes .....	20
<b>3. Electrical data</b>	<b>21</b>
<b>4. Installation</b>	<b>22</b>
4.1. Prior to installation .....	22
4.2. Installing the position encoder .....	23
4.3. Checks after installation .....	26
4.4. Testing unit ZTG1 .....	27
4.4.1. Connections .....	27
4.4.2. Test procedures .....	28
<b>5. Identification</b>	<b>30</b>
<b>6. Index</b>	<b>31</b>
<b>7. Summary of supplementary documentation</b>	<b>34</b>

## 1. Applications and features

Main spindle position encoders are made up of a measuring wheel and a non-contact sensor. The measuring wheel is mounted directly onto the spindle, the sensor onto the spindle housing.

*High resolution* INDRAMAT's AC main spindle controllers and digital AC servo drives evaluate the sensor signals and measure spindle position with a resolution of up to  $1/4.000.000$ th of a revolution within the total speed range.

*An economic solution* The determination of the spindle position needed for C-axis operations, thread-cutting or spindle positioning is advantageously handled with the use of only one encoder. The extremely high position resolution over the full speed range makes this possible. And, in comparison to other conventional encoders, costs and work are saved.

*Installation requirements* The protection category of the high-resolution main spindle position encoder is IP00 due to its design. The ambient conditions needed for a faultless and reliable functioning of the encoder, therefore, depend entirely upon the spindle housing!

## 1.1. Applications

### Spindle position determination

The main spindle drives KDA, TDA, RAC, and the digital drives DDS, DKS and DKR use the high-resolution main spindle position encoder to determine the position of the spindle.

The determined spindle position can be transmitted to the NC controller either by means of

- a SERCOS interface, or,
- the incremental encoder output of the drive controller.

Spindle position determination makes it possible for the main spindle drive to perform such tasks as spindle positioning, C-axis operation and thread cutting.

### Drive with SERCOS interface




Figure 1.1: Basic principle of application of a high-resolution main spindle position encoder with SERCOS interface to the NC controller

The SERCOS interface transmits the actual position of the spindle to the controller with an accuracy of up to 0.0001 angular degrees. The NC controller can also read out the actual speed and torque values of the drive. The NC controller can control the drive by means of position, speed or torque command values.

*Drive with incremental encoder output*




Figure 1.2: Basic principle of application of a high-resolution main spindle position encoder with an incremental encoder interface to the NC controller

The incremental encoder output transmits the actual spindle position to the NC controller with an accuracy of up to 0.001 angular degrees.

The incremental encoder output works in the same fashion as a conventional incremental encoder except that parameters can be used to set the encoder lines per revolution (1pr).

## 1.2. Components and installation variations

### *Position encoder with sensor mounting ring*

A factory-set sensor with mounting ring is used in those applications where the installation position of the sensor is axially accessible. The mounting ring is fed over the end of the spindle. Once secured into place, the distance between the sensor and the measuring wheel is immediately correctly set.




Figure 1.3: Parts of the high-resolution main spindle position encoder (with mounting ring)




Figure 1.4: Installation variations of a high-resolution main spindle position encoder with sensor mounting ring

*Position encoder without sensor mounting ring*

A sensor without mounting ring must be used in all those applications where it is not possible to feed a mounting ring over the spindle. The correct distance between sensor and measuring wheel, in this case, must be set at the time of mounting on site.




Fig.1.5: Components of a high-resolution main spindle position encoder (without mounting ring)




Figure 1.6: Installation variations of a high-resolution main spindle position encoder without sensor mounting ring



*Mounting the measuring wheel*




Figure 1.7: Affixing the screws

Because of the mechanical dimensions, it is not possible to affix measuring wheel MH2-128 with screws!




Figure 1.8: Mounting using adjusting key and thread

### 1.3. Designs

*Measuring wheel sizes* The high-resolution main spindle position encoders are available in three sizes. The external diameters of the measuring wheels are coordinated with the sizes of the 1MB frameless spindle motors. The bore diameters are selected to correspond to the external diameter of the spindle.





Figure 1.9: Measuring wheel sizes and bore diameters

*Sensor* The sensor without mounting ring is available for all three measuring wheel sizes. The sensor with mounting ring is only available for measuring wheel sizes MH2-256-... and MH2-512-... !


## 2. Mechanical data

### 2.1. Dimensional data



MB128.tif (aus CAD-Z.Nr.: 105-0687-3002-01)

Figure 2.1: Dimensions and connecting dimensions of the position encoder with measuring wheel MH2-128 and sensor SH2-128 without mounting ring



MB256N.tif (aus CAD-Z.Nr.: 105-0681-3002-02)

Figure 2.2: Dimensions and connecting dimensions of the position encoder with measuring wheel MH2-256 and sensor SH2-256 without mounting ring




Form and position tolerances:  
 (1) maximum concentricity and plane tolerances of the measuring wheel centering to shaft-bearing seat  
 A = 0.01 mm

$\phi d1$  - Available drill hole dia. of measuring wheel MH

$\phi d2^{H6}$  - Available hole circle dia. for fixing holes

Wheel 1H2-512-5-XXX Y



$\phi d1^{H6}$ [mm]	E ( $\phi d2=112$ )	D ( $\phi d2=132$ )	C ( $\phi d2=200$ )
$\phi 80^{H6}$	X	X	
$\phi 85^{H6}$	X	X	
$\phi 90^{H6}$	X	X	
$\phi 95^{H6}$	X	X	
$\phi 100^{H6}$	X	X	
$\phi 105^{H6}$		X	
$\phi 110^{H6}$		X	X
$\phi 115^{H6}$		X	X
$\phi 120^{H6}$		X	X
$\phi 125^{H6}$			X
$\phi 130^{H6}$			X
$\phi 135^{H6}$			X
$\phi 140^{H6}$			X
$\phi 145^{H6}$			X
$\phi 150^{H6}$			X
$\phi 155^{H6}$			X
$\phi 160^{H6}$			X
$\phi 165^{H6}$			X
$\phi 170^{H6}$			X
$\phi 175^{H6}$			X
$\phi 180^{H6}$			X



MBa512oM.tif (aus CAD-Z.: 105-0682-2004-01/C,D,E)

Figure 2.4: Dimensions and connection dimensions of the position encoder with measuring wheel MH2-512 and sensor SH2-512 without mounting ring

Detail Y: M 1:1



MBb512oM.tif (aus CAD-Z.: 105-0682-2004-01/C,D,E)

Form and position tolerances:

(1) maximum concentricity and plane tolerances of the measuring wheel centering to shaft-bearing seat

A = 0.01 mm

(2) maximum concentricity tolerances of the mounting ring pilot to the housing-bearing seat


B = 0.01 mm

$\phi d1$  - Available bore hole dia. with measuring wheel MH

$\phi d2^{H6}$  - Available hole circle dia. for fixing bore holes

Wheel MH2-512-5-XXX Y


$\phi d1^{H6}$ [mm]	E ( $\phi d2=112$ )	D ( $\phi d2=132$ )	C ( $\phi d2=200$ )
$\phi 80^{H6}$	x	x	
$\phi 85^{H6}$	x	x	
$\phi 90^{H6}$	x	x	
$\phi 95^{H6}$	x	x	
$\phi 100^{H6}$	x	x	
$\phi 105^{H6}$		x	
$\phi 110^{H6}$		x	x
$\phi 115^{H6}$		x	x
$\phi 120^{H6}$		x	x
$\phi 125^{H6}$			x
$\phi 130^{H6}$			x
$\phi 135^{H6}$			x
$\phi 140^{H6}$			x
$\phi 145^{H6}$			x
$\phi 150^{H6}$			x
$\phi 155^{H6}$			x
$\phi 160^{H6}$			x
$\phi 165^{H6}$			x
$\phi 170^{H6}$			x
$\phi 175^{H6}$			x
$\phi 180^{H6}$			x



MBa512mM.tif (aus CAD-Z.: 105-0682-2003-01/C,D,E)

Figure 2.5: General and connecting dimensions of the position encoder with measuring wheel MH2-512 and sensor SH2-512 with mounting ring





MBb512mM.tif (aus CAD-Z.: 105-0682-2003-01/C,D,E)




Figure 2.6: Dimensions of sensor connecting cable IN356/...

## 2.2. Technical data

Data of the measuring wheel and sensor

Designation	Sensor type	SH2-128-5-...	SH2-256-5-...	SH2-512-5-...
	Wheel type	MH2-128-5-...	MH2-256-5-...	MH2-512-5-...
Permissible mechanical maximum speed in min <sup>-1</sup>		60 000	30 000	15 000
Permissible ambient temperature range in °C				
Permissible humidity of ambient atmosphere per DIN 40 040		Humidity classification F		
Mandatory protection category after installation		IP 54		
Perm. axial changes in distance between where sensor is screwed on on the spindle box and the wheel plane surface on spindle		+0.4 -0.2	+0.4 -0.2	+0.7 -0.3
Supply voltage		DC 5 V ±5% (Current must be limited to 200 mA!)		
Balance quality per VDI 2060		Q1		

Figure 2.7: Compilation of technical data for the measuring wheel and sensor

Position encoder data in connection with drives

Designation	Sensor type	SH2-128-5-...	SH2-256-5-...	SH2-512-5-...
	Wheel type	MH2-128-5-...	MH2-256-5-...	MH2-512-5-...
Absolute position measuring accuracy with centric installation				
additional position measuring error with eccentric installation		0.02 deg. per 0.01 mm eccentricity	0.01 deg. per 0.01 mm eccentricity	0.005 deg. per 0.1 mm eccentricity
Maximum speed in combination with drive controller in min <sup>-1</sup>	KDA/TDA RAC	25000	25000	12500
	DDS/DKS DKR	50000	25000	12500

Figure 2.8: Compilation of technical data in combination with drives

### 2.3. Type codes




Figure 2.8: Type codes for measuring wheel MH2




Figure 2.9: Type codes for sensor SH2




Figure 2.10: Type codes for the sensor connecting cable

### 3. Electrical data

Depending upon the spindle drive, the high-resolution main spindle position encoder can be used as either a motor feedback (as in the 1MB frameless spindle motor), or as a spindle feedback (as in spindles with 2AD main spindle motors). In both cases, it signals spindle position to the main spindle drive.

*Terminal connection diagram*

The terminal connection diagrams for these feedback connections are the same regardless of motor type (1MB or 2AD). These diagrams are summarized and can be found in the document entitled: „Electrical connections of main spindle drives, project planning manual,“ doc. no. 209-0042-4111. They apply to all main spindle drives and can be easily located using the search code (see below for example). These plans are, therefore, absolutely necessary when developing the machine circuit diagrams!




Figure 3.1: Schematic terminal diagram for spindle drives with 2AD




Figure 3.2: Schematic terminal diagram for spindle drive with 1MB

## 4. Installation

### 4.1. Prior to installation

*Handling* The high-resolution main spindle position encoder is a high-precision component. Adhere to the following guidelines when handling it.



**Handle measuring wheel and sensors with care!**

**Even the most minor damage to the gear teeth make them unusable.**

**To avoid damage:**

- store parts in the package
- do not remove parts from packaging before they are to be installed



**To avoid accidents, never turn the spindle without the prescribed measuring wheel mountings (see section 4.2., installing the measuring wheel).**

*Installation aids*

- set of hexagonal screw drivers
- torque wrench (0.7 ... 6 Nm)
- 0.2 mm feeler gauge (in the case of sensors without mounting rings)
- toothed wheel encoder testing unit ZTG1 (in the event a function test needs to be run), and feedback cable IKS 315

*What is delivered*

- Measuring wheel MH2-...-5-....
- Sensor SH2-...-5-..
- Sensor connecting cable IN 356/... including
  - O-ring 20 x 1.5 (Viton)
  - 4 metric M screws 2.5 x 8 DIN 7985

*Identification*

See section 5.

*Verifications*

- Is there any visible damage on the components of the encoder?
- Measuring wheel:
  - Does the fixing point for the measuring wheel correspond to the fixing dimensions (see measuring wheel Figures 2.1 through 2.5) with respect to diameter d1, concentricity and plane course (see Figure 4.1 or 4.2).
- Sensor without mounting ring:
  - Do dimensions l3 and r (see Figure 4.4) on the spindle housing agree with the fixing dimensions (see sensor Figure 2.1, 2.2 or 2.4)?
- Sensor with mounting ring:
  - Does the inside diameter of the mounting ring agree with the pilot diameter d3 (see Figure 4.3)?
  - Does dimension l2 (see Figure 4.3) on the spindle housing agree with the fixing dimensions (see sensor type Figure 2.3 or 2.5)?

### 4.2. Installing the position encoder

*Measuring wheel*

- Clean the measuring wheel drill hole and its fixing point on the spindle!
- Push the wheel onto its fixing point on the spindle without canting it.
- The measuring wheel must be attached to the spindle with a pressure force of  $F_A \geq 2000 \text{ N!}$




Figure 4.1: Installing the measuring wheels using fixing screws




Figure 4.2: Installing the measuring wheel using an adjusting key

*Sensor with mounting ring*

Screw the sensor with mounting ring onto the spindle housing using three fixing screws ( $M_A = 6 \text{ Nm}$ ).




Figure 4.3: Installing the sensor with mounting ring

*Sensor without mounting ring*

First, screw the sensor only loosely onto the spindle housing using two fixing screws.



**Do not now turn the spindle with the already mounted measuring wheel!**

**The sensor may bear on the stationary measuring wheel during mounting!**




Figure 4.4: Installing a sensor without a mounting ring



Detach the loosely mounted sensor from the measuring wheel. Turn the wheel so that the zero-impulse (grooved pin next to the gear teeth) is not within sensor range. Guide the feeling gauge (0.2 mm) carefully between the measuring wheel and the clearance blocks that are on the sensor housing. With slight pressure, lean the sensor housing with feeler gauge against the toothed wheel. The feeler gauge guarantees that a defined clearance is maintained.

Tighten the fixing screws ( $M_A = 2.9 \text{ Nm}$ ). Pull the feeling guide carefully out in an axial direction.




Figure 4.5: Adjusting the clearance between sensor and measuring wheel

*Sensor connecting cable*

Screw the socket with O-ring onto the spindle housing (tightening torque of the four screws:  $M_A = 0.7 \text{ Nm}$ ). Plug the connector onto the sensor circuit board!



**Do not damage the sensor connecting cable! It must not rub against any rotating parts!**

**Install it spatially separated from power conducting lines!**

### 4.3. Checks after installation



#### Danger of damage!

**Do not let the teeth of the measuring wheel touch either the spindle housing or the sensor!**

- Carefully check the clearance of the measuring wheel by turning the spindle 360°!
- Check the concentricity and plane course of the measuring wheel!




Figure 4.6: Checking concentricity and plane course



**The concentricity and plane course tolerances of the spindle and the measuring wheel can add up during installation in such a way that the listed values are exceeded. In this case, remove the measuring wheel, rotate it, and re-install it.**

- Check dimensions I2 (see Figure 4.3) and I3 (see Figure 4.4) with respect to the measuring wheel!

## 4.4. Testing unit ZTG1

Testing unit ZTG1




Figure 4.7: View onto the ZTG1 with allocation of terms

### 4.4.1. Connections




Figure 4.8: Checking functions with the encoder testing unit ZTG1

- Connect sensor and testing unit ZTG1 with each other over sensor connecting and motor feedback cables (IKS 315).
- Connect ZTG1 to the 220 V mains and turn mains switch on. The yellow LED "+5V" must light up.



**Wait approximately three minutes after switching the ZTG1 on. This is due to transient thermal reactions in the sensor!**

#### 4.4.2. Test procedures

##### Checking the amplitude

- Turn the selection dial to “amplitude” or “cosine” or “sine”.
- Turn the spindle by hand (approx. 10 ... 50 min<sup>-1</sup>).
- Read and record the display and compare to the command value range (see Figure 4.9).

##### Checking the offset values

- Turn selection dial to “offset” of “cosine” or “sine”.
- Turn the spindle by hand (approx. 10 ... 50 min<sup>-1</sup>).
- Read and record the display and compare with command value range (see Figure 4.9).
- Turn selection dial to “zero impulse”, “offset”.
- Adjust the spindle so that the zero impulse indicator is outside of the sensor range. Do not turn spindle!
- Read and record the display and compare with command value range (see Figure 4.9).
- Turn spindle by hand (approx. 10 ... 50 min<sup>-1</sup>).  
The green LED „zero impulse“ display should flash briefly when the zero impulse indicator is moved past the sensor. The red LED „zero impulse width“ display must not light up.

	Command values (in V) at		Display in V $\vartheta_{\text{Motor}} \approx \dots$	Value within command value range? (yes/no)	
	$\vartheta_{\text{Motor}} \approx 20^\circ\text{C}$	$\vartheta_{\text{Motor}} \approx 150^\circ\text{C}$			
Amplitude	cosine	7.0 ... 8.0	3.5 ... 4.5		
	sine	7.0 ... 8.0	3.5 ... 4.5		
Offset	cosine	-0.5 ... +0.5	-1.5 ... +1.5		
	sine	-0.5 ... +0.5	-1.5 ... +1.5		
	0 impulse	-0.5 ... +0.5	-1.5 ... +1.5		
LED (green) "0 impulse"	Quick flashing with slowly turning spindle?			<input type="checkbox"/> Yes	<input type="checkbox"/> No (Error)
LED (red) "0 impulse" width	Lights up with slowly turning spindle?			<input type="checkbox"/> No	<input type="checkbox"/> Yes (Error)

Figure 4.9: Checklist for testing a main spindle position encoder with ZTG1

*Function tests checked out?* The spindle is now ready for commissioning!

*Function tests did not check out?* If the amplitude values are not within the permissible value range, then the clearance of sensor to measuring wheel must be readjusted (see Figure 4.5).



**Do not release the screws that have been varnished over!  
This could cause a defect in the sensor!**



**The amplitude values drop the greater the distance between sensor and measuring wheel!**

- If the amplitude values continuously range at zero, then check the feedback or sensor connecting cable! (See document “Electrical connections of main spindle drives, Project planning manual, doc. no.: 209-0042-4111).
- If the offset values exceed the permissible range, even though the amplitude values are within the permissible range, then exchange the sensor.
- If the green LED „zero impulse“ display does not light up:
  - a) The zero impulse indicator on the measuring wheel could either be damaged or broken off  
Remedial action: replace measuring wheel!
  - b) The sensor could be defective.  
Remedial action: replace sensor!
  - c) The sensor has been improperly installed.
- If the red LED „zero impulse width“ lights up:
  - a) The manually set spindle speed could be too low.
  - b) The zero impulse indicator on the measuring wheel could be damaged.  
Remedial action: replace measuring wheel!
  - c) The sensor is defective.  
Remedial action: replace sensor!

*Faults cleared?* Re-run the function tests (see the beginning of section 4.4.2.).

## 5. Identification

Sensor




Figure 5.1: Sensor rating plate and fixing point (example)

Sensor connecting cable




Figure 5.2: Cable identification on the sensor connecting cable (example)

Measuring wheel




Figure 5.3: Inscription on the measuring wheel (example)

## 6. Index

### Symbole

1MB frameless spindle motor 21  
2AD main spindle motor 21

### A

Absolute position measuring 19  
Adjusting key 9  
Ambient temperature 19

### B

Balance quality 19  
Bore diameter 10  
Bushing 9

### C

C-axis operations 4  
Checking the amplitude 28  
Checking the offset values 28  
Clearance blocks 25  
Clearance sensor-measuring wheel 25  
Concentricity and plane course of the measuring wh 26

### F

Feedback connections 21  
Fixing screws 9

### H

Handling 22

### I

Identification 22, 30  
Incremental encoder output 5, 6  
Installation 22  
Installation aids 22  
Installation variations 7  
Installing the measuring wheel using an adjusting 23  
Installing the measuring wheels using fixing screw 23  
Installing the sensor with fitting ring 24  
Installing the sensor without fitting ring 24

### M

Main spindle drive controller 21  
Maximum mechanical speed 19  
Measuring wheel 9  
Measuring wheel sizes 10  
Motor feedback 21  
Mounting the measuring wheel 9

### P

Plane surface 10

**S**

Screws 9  
Sensor fitting ring 7  
Sensor housing 25  
Sensor rating plate 30  
Sensor with fitting ring 7, 24  
Sensor without fitting ring 8, 24  
SERCOS interface 5  
Spindle 9  
Spindle feedback 21  
Spindle housing 9  
Spindle positioning 5  
Supply voltage 19

**T**

Technical data 19  
Test protocol 28  
Type codes 20

**Z**

ZTG1 27



---

## Notes

# 7. Summary of supplementary documentation





Figure 7.1: Summary of supplementary documentation


**AC main spindle drives with regulated 1MB frameless spindle motors**



- Selection data
- Summary of the AC main drive system
  - Power levels
  - AC main spindle drive functions
  - Selection protocols and order lists
  - Product availability

Doc. no. 9.567.012.4

**AC spindle drives with regulated 2AD asynchronous motors and 2K planetary gearboxes**




- Selection data
- Summary of the main spindle drive system
  - Power levels
  - Order guidelines

Doc. no. 9.567.022.4

**Selection**  
(details, ordering)

You have this document ...




**Frameless spindle motor**

Project planning

- Machine construction plans
- Integrating into the cooling system
- Electrical and coolant connections
- Delivery


- 1MB 160, Doc. no. 9.576.014.4
- 1MB 200, Doc. no. 9.576.016.4
- 1MB 240/241, Doc. no. 9.576.015.4
- 1MB 310/312, Doc. no. 9.576.008.4
- 1MB 375, Doc. no. 9.576.007.4



Installation guidelines

- Delivery, handling, transport
- Assembly
- Cooling guidelines

- Stator, Doc. no. 9.600.063.4
- Rotor, Doc. no. 9.600.062.4



**Supplementary documentation**

- High-resolution main spindle position encoder Project planning Doc. no. 209-0042-4119
- Incremental encoder output - IGS Doc. no. 9.568.015.4
- High-resolution encoder branching - HGV Doc. no. 9.568.010.4
- Built-on absolute encoder for 2AD 132, 2AD 160, 2AD 180 Dok.Nr. 9.568.020.4

**Project planning**  
(construction, assembly, installing the machine)

**Applications of the main spindle drive**  
(Commissioning, operating, diagnostics)

