

MT-CNC Auxiliary Function Output V16

Description

DOK-MT*CNC-AUX*FUN*V16-ANW1-EN-P

Title Auxiliary Function Output

Kind of dokument Description

Docu-Type DOK-MT*CNC-AUX*FUN*V16-ANW1-EN-E1,44

Internal filing remarks

- Mapped 5 Reg 8
- M508163E.pdf
- Drawing no.: 109-0768-4163-00/E

Purpose of this document This document describes the extended functionality of the Auxiliary Function Output.

Reference This electronic document is based on the hardcopy document with document desig.: DOK-MT*CNC-AUX*FUN*V16-ANW1-EN-P

Revision	Date	Remarks
109-0768-4163-00	11/95	New issue
DOK-MT*CNC-AUX*FUN*V16-ANW1-EN-E1,44	06/97	1st E-Dok

Copyright © INDRAMAT GmbH, 1996

Copying this document, and giving it to others and the use or communication of the contents thereof without express authority, are forbidden. Offenders are liable for the payment of damages. All rights are reserved in the event of the grant of a patent or the registration of a utility model or design (DIN 34-1).

The electronic documentation (E-doc) may be copied as often as needed if such are to be used by the customer for the purpose intended.

Published by INDRAMAT GmbH • Bgm.-Dr.-Nebel-Str. 2 • D-97816 Lohr a. Main
 Telefon +49 (0) 9352/40-0 • Tx 689421 • Fax +49 (0) 9352/40-4885

Abt. ENC (GL)

Table of Contents

1 Introduction	1-1
2 M, Q, S, T and E Functions	2-1
2.1 Basics.....	2-1
2.2 M Functions.....	2-1
2.3 Q Functions.....	2-3
2.4 S Functions	2-3
2.5 T Function	2-4
2.6 E Function	2-4
3 Machine Parameters	3-1
3.1 Basics.....	3-1
3.2 Global M Function Mode	3-1
3.3 Global Q Function Mode	3-2
3.4 S Function Mode	3-2
3.5 T/E Function Mode.....	3-2
3.6 Deviating M and Q Functions	3-2
3.7 M Function Groups.....	3-3
4 Output and Acknowledgement Behaviour	4-1
4.1 Normal Auxiliary Functions.....	4-1
Output and Acknowledgement 'at the Beginning of a Movement'	4-1
Output and Acknowledgement 'at the End of the Movement'	4-1
Output 'at the Beginning of the Movement' and Acknowledgement 'at the End of the Movement'	4-2
4.2 Swift Auxiliary Functions.....	4-3
General.....	4-3
Swift M and Q Function Output	4-3
Inquiring Swift M and Q Functions.....	4-4
Swift S, T and E Function Output	4-5
No Auxiliary Function Output.....	4-5
5 PLC User Programming	5-1
5.1 Inquiring a Change in the Auxiliary Functions (with Group Specification)	5-1
5.2 Direct Inquiry of an Auxiliary Function (Specifying the Number)	5-2
5.3 Direct Acknowledgement of an Auxiliary Function (Specifying a Number)	5-3
5.4 Reading an Auxiliary Function Number.....	5-4
5.5 Acknowledging an Auxiliary Function (Specifying the Group)	5-7
5.6 Sequence of the M00, M01, M02, and M30 Function Output.....	5-8

M Functions M00 and M015-8
M Functions M02 and M305-8

6 Index6-1

7 Table of Figure7-1

1 Introduction

Reducing machining time The primary and secondary times of a machine can only be reduced by a parallel or a swifter machining sequence, including all auxiliary and utility functions. Due to the specified number of axes and the arrangement of tools and workpieces, parallel machining is not possible for the majority of machine tools. There is a large number of obstacles to increasing the speed of machining; the mechanical part, in particular, frequently meets its limits (machine structure, bearings, tools, ...).

Time-optimized processing of auxiliary functions Thus, time-optimized output and processing of auxiliary functions is of supreme importance to increasing the productivity of a manufacturing plant. This is even more important with machining centres that are capable of high-speed (cost-intensive) machining.

2 M, Q, S, T and E Functions

2.1 Basics

Available auxiliary functions The following functions are available in the MT-CNC:

- Three-digit M functions (M0 through M999)
- Four-digit Q functions (Q0 through Q9999)
- S functions with up to five integer and up to two fractional part digits (S0.00 through S99999.99; the NC only transfers the integers to the PLC)
- Seven-digit T functions (T0 through T9999999)
- One-digit E functions (E0 through E9)

Within an NC block, the user may program a maximum of six auxiliary functions. In each block, a maximum of

- 6 M functions,
- 1 Q function,
- 1 S1 function,
- 1 S2 function,
- 1 S3 function,
- 1 T function and
- 1 E function

are permitted.

Example

```
N0423 M103 S1 200 M204 S2 400 M319 S3 0 ;activating spindles 1 and 2 and
position tool spindle 3
```

2.2 M Functions

Task 'M functions' can be used for activating various machine functions. Some M functions have a fixed functionality assigned:

- M0 unconditional stop
- M1 conditional stop
- M2 end of program with reset
- M30 end of program with reset
- Mj03spindle j clockwise $j \in \{', '1', '2', '3'\}$
- Mj04spindle j counter-clockwise
- Mj05spindle j halt
- Mj13spindle j clockwise and coolant/lubricant ON
- Mj14spindle j counter-clockwise and coolant/lubricant ON
- Mj19positioning spindle j
- Mj40automatic gear changes for spindle j
- Mj41gear level 1 for spindle j
- Mj42gear level 2 for spindle j
- Mj43gear level 3 for spindle j
- Mj44gear level 4 for spindle j

spindle speed	5	2
spindle position	3	2
constant cutting speed	5	2
speed limitation	5	2
grinding wheel peripheral speed	3	2

- Setting parameter values** The machine manufacturer defines output time and acknowledgement behaviour of the individual S functions.
- Programming**
- The same spindle index 'j' that has been stored in the axis parameters of the spindle designation must be programmed for the S functions.
 - An NC block may contain up to three S functions. The S functions must have different axis indices.
- Peculiarities**
- The NC always starts the execution of the motion of NC-controlled spindles at the beginning of the feed movement, irrespective of the selected output and acknowledgement behaviour of the related S or M function. If the spindle movement has been initiated by a normal M function, the NC waits at the end of the feed movement until the expected spindle value has reached the programmed final value.
 - The NC continues program execution without this check if the spindle movement has been caused by a swift M function (MQj03, MQj04, MQj05, MQj13, MQj14; $j \in \{1, 2, 3\}$).
 - Using the parameters, the machine manufacturer can output the S functions to the PLC for both, PLC-controlled spindles and NC-controlled spindles.

2.5 T Function

- Task** The '**T function**' specifies the tool and/or location number of the next tool that is to be changed in.
- Syntax** Txxxxxx $x \in \{0 \text{ through } 9999999\}$
 T=Variable
 Variable=T
- Setting parameter value** The machine manufacturer defines output time and acknowledgement behaviour of the T/E functions.
- Programming** An NC block may contain a maximum of one T function.
- Peculiarities** Provided that tool management has not been selected, the user may employ the T functions like any other auxiliary function for implementing tasks.

2.6 E Function

- Task** The '**E function**' is used for selecting the current tool edge.
- Syntax** Ex $x \in \{0 \text{ through } 9\}$
 E=Variable
 Variable=E
- Setting parameter values** The machine manufacturer defines output time and acknowledgement behaviour of the T/E functions.
- Programming** An NC block may contain a maximum of one E function.
- Peculiarities** Provided that tool management has not been selected, the user may employ the E functions like any other auxiliary function for implementing tasks.

3 Machine Parameters

3.1 Basics

Options	The parameters below are used for defining the output and acknowledgement behaviour of the M, Q, S, T, and E functions. The output behaviour can be specified as 'at the beginning of the movement', 'at the end of the movement', or 'no output'. The acknowledgement behaviour can be 'at the beginning of the movement', 'at the end of the movement', or 'later'.
Output behaviour	If the machine manufacturer defines the output behaviour as 'at the beginning of the movement' or 'at the end of the movement', the NC transfers the auxiliary function concerned as a normal auxiliary function to the PLC and, if necessary, waits for the acknowledgement at the beginning or at the end of the movement. If the machine manufacturer defines the output behaviour as 'no output', the auxiliary function concerned will not reach the PLC.
Acknowledgement behaviour	If the acknowledgement behaviour is defined as 'at the beginning of the movement' or 'at the end of the movement', the NC waits at the beginning or at the end of the movement for the acknowledgement of the functions concerned. If, in contrast, the machine manufacturer defines the acknowledgement behaviour as 'later', the NC transfers the auxiliary function as a swift auxiliary function to the PLC and continues program execution without interruption (provided that the user has programmed this feature by a 'Q' in the function designation). If the user does not insert a 'Q' in the function designation, the NC only continues program execution at the end of the movement after the PLC has acknowledged the output auxiliary function.

3.2 Global M Function Mode

Name	Global M function mode	
Number	A00.087	
Parameter	System parameter	
Value range	Output behaviour:	at the end, at the beginning, no output
	Acknowledgement behaviour:	at the end, at the beginning, later
Default value	Output behaviour:	at the end
	Acknowledgement behaviour:	at the end
Unit	-	
Purpose	The ' Global M function mode ' parameter defines the output behaviour and acknowledgement behaviour of all M functions across the processes.	

Instruction:

- Up to 40 M functions with an output and acknowledgement behaviour that differs from the global M function mode may be defined for each process.
- The M functions 'M0', 'M01', 'M02', 'M30' cannot be entered. The NC always outputs these functions at the end and waits until the PLC has acknowledged them before it continues with executing the next block.
- The NC always outputs the gear shift functions 'Mj40' through 'Mj44' ($j \in \{1, 2, 3\}$) at the beginning of a block. If a multi-stage gearbox exists, the NC waits at the end of the movement, and continues program execution only after the output M function has been acknowledged. Independently of the selected behaviour, the NC always responds like this if the M functions 'Mj40' through 'Mj44' are used for selecting gears. The NC only considers the entered output and acknowledgement behaviour of

the M functions 'Mj40' through 'Mj44' if these functions are not used for changing gears.

3.3 Global Q Function Mode

Name	Global Q function mode	
Number	A00.088	
Parameter	System parameter	
Value range	Output behaviour:	at the end, at the beginning, no output
	Acknowledgement behaviour:	at the end, at the beginning, later
Default value	Output behaviour:	at the end
	Acknowledgement behaviour:	at the end
Unit	-	
Purpose	The ' Global Q function mode ' parameter defines the output behaviour and acknowledgement behaviour of all Q functions across the processes.	
Hinweis:	Up to 40 Q functions with an output and acknowledgement behaviour that differs from the global Q function mode may be defined for each process.	

3.4 S Function Mode

Name	S function mode	
Number	A00.089	
Parameter	System parameter	
Value range	Output behaviour:	at the end, at the beginning, no output
	Acknowledgement behaviour:	at the end, at the beginning, later
Default value	Output behaviour:	no output
	Acknowledgement behaviour:	later
Unit	-	
Purpose	The ' S function mode ' parameter defines the output behaviour and acknowledgement behaviour of all S functions across the processes.	

3.5 T/E Function Mode

Name	T/E function mode	
Number	A00.090	
Parameter	System parameter	
Value range	Output behaviour:	at the end, at the beginning, no output
	Acknowledgement behaviour:	at the end, at the beginning, later
Default value	Output behaviour:	no output
	Acknowledgement behaviour:	later
Unit	-	
Purpose	The ' T/E function mode ' parameter defines the output behaviour and acknowledgement behaviour of all T and E functions across the processes.	

3.6 Deviating M and Q Functions

Name	<ul style="list-style-type: none"> • Deviating M functions • Deviating Q functions
Number	Bxx.046 Bxx.047

Parameter	Process parameter (in list form)	
Value range	Output behaviour:	at the end, at the beginning, no output
	Acknowledgement behaviour:	at the end, at the beginning, later
Default value	Output behaviour:	at the end
	Acknowledgement behaviour:	at the end
Unit	-	
Purpose	These two parameters, that are offered in the form of a list, enable up to 40 M function and up to 40 Q functions to be defined in each process. The output and acknowledgement behaviour of these functions differ from the global function behaviour.	

3.7 M Function Groups

Name	M functions of M function group 5	
	.	
	M functions of M function group 10	
	M functions of M function group 14	
	M functions of M function group 15	
Number	Bxx.048	
	.	
	Bxx.053	
	Bxx.054	
	Bxx.055	
Parameter	Process parameter	
Value range	3 through 999	
Default value	M functions of M function group 5	7, 8, 9, 107, 108, 109
	M functions of M function group 6	207, 208, 209
	M functions of M function group 7	307, 308, 309
	M functions of M function group 8	10, 11, 110, 111
	M functions of M function group 9	210, 211
	M functions of M function group 10	310, 311
	M functions of M function group 14	46, 47
	MM functions of M function group 15	48, 49
Unit	-	
Purpose	These parameters enable the machine manufacturer to define the M functions that belong to the groups 5 through 10, 14, and 15.	

Instruction:

- Each group can have a maximum of 12 M functions.
- An M function that belongs to the program control, spindle control, or gear change command group must not be assigned to the groups 5 through 10, 14, and 15.
- Multiple entries are not permitted.
- Please note when allocating the M functions to the M function groups, that each NC block from each M function group may only contain one M function. This must also be observed for M function group 16 that has automatically all functions assigned that have not been allocated to another group.

4 Output and Acknowledgement Behaviour

4.1 Normal Auxiliary Functions

Output and Acknowledgement 'at the Beginning of a Movement'

Effect The NC stops the movement at the end of the previous block, and transfers the auxiliary function to the PLC at the beginning of the current block. The NC only performs the programmed feed movements of the active NC block after the PLC user program has sent an acknowledgement.




Fig. 4-1: Input of auxiliary function 'at the beginning of the movement' and acknowledgement 'at the beginning of the movement'

Output and Acknowledgement 'at the End of the Movement'

Effect Only after the PLC has acknowledged the auxiliary function, the NC transfers the auxiliary function 'at the end of the movement' to the PLC and begins processing the

- tool management commands
- event commands,
- process control commands, and
- program control commands.

The NC transitions to the next block after these additional commands have been executed.




Fig. 4-2: Input of auxiliary function 'at the beginning of the movement' and acknowledgement 'at the beginning of the movement'



⇒ Within an NC block, the NC always issues the 'M0', 'M1', 'M2' and 'M30' program control commands and the 'Mj40' through 'Mj44' ($j \in \{', '1', '2', '3\}$) gear changing functions (if there is a multi-stage gearbox for spindle 'j') at the end of the movement, and waits for them to be acknowledged before it processes the tool management, event, process control, and program control commands.



⇒ Only auxiliary functions that are output and acknowledged at the end of the movement may be used for activating and de-activating follower and Gantry axes and main spindle synchronization.

Output 'at the Beginning of the Movement' and Acknowledgement 'at the End of the Movement'

Effect Auxiliary function output 'at the beginning of the movement' and acknowledgement 'at the end of the movement' help in asynchronous processing of auxiliary functions since the NC only stops program execution if the auxiliary function has not yet completely been processed at the end of the movement.

An auxiliary function that shall be in effect before the axes start moving must be programmed in the preceding block.




Fig. 4-3: Auxiliary function output 'at the beginning of the movement' and acknowledgement 'at the end of the movement'

Short motion blocks Where very short motion blocks are concerned, whose execution takes less time than the execution of the programmed auxiliary function and/or the safe recognition of the auxiliary function (at least one PLC cycle), the NC interrupts the further execution of the block until the auxiliary function is acknowledged at the end of the movement. Only after acknowledgement has been received, the NC processes the auxiliary commands (tool management, event, process control, and program control commands) and transitions to the next NC block.

To avoid jerky interruptions of the movement, the path velocity 'F' must be reduced accordingly or the auxiliary function concerned must be output as a swift auxiliary function.

This type of auxiliary function output permits only a limited execution of contouring mode. Even if speed-optimized block transition (G08) has been selected, the NC reduces the path velocity at the end of the movement to the computed maximum velocity jump in order to be able to stop the axes when the acknowledgement fails to appear.




Fig. 4-4: Typical inquiry of swift M and Q functions

Swift S, T and E Function Output

Task In contrast to the M and Q functions, the S, T, and E functions are not used for activating different functions.

S functions	T functions	E functions
are exclusively used for specifying <ul style="list-style-type: none"> • spindle speed, • spindle position, • surface speed, • speed limitation • grinding wheel peripheral speed 	are used for specifying <ul style="list-style-type: none"> • tool or location number 	are used for specifying <ul style="list-style-type: none"> • tool edge number

Programming The user cannot use an appended 'Q' for influencing the output behaviour of the S, T, or E functions that has been defined by the machine manufacturer. If the user employs the appendix 'Q' for these functions, the user interface generates an error message during syntax check.

Likewise, using an appended 'W' for waiting for the execution of an S, T, or E function is not possible either.

No Auxiliary Function Output

Task Usually, the machine manufacturer only selects '**no auxiliary function output**' for auxiliary functions that have no functions allocated in the PLC (e.g. the spindle control commands).

Programming M and Q functions that are not to be output can be programmed with or without an appended 'Q'.

5 PLC User Programming

5.1 Inquiring a Change in the Auxiliary Functions (with Group Specification)

General Using the standard functions

- M_ALL,
- Q_ALL,
- S_ALL,
- T_ALL and
- E_ALL,


the PLC is able to recognize a newly output auxiliary function. These standard functions can be used for skipping program sections in which auxiliary functions are executed if there is no change, thus permitting time-optimized program execution.

If there is a change, the PLC can either

- directly inquire (M_FKT, Q_FKT, S_FKT, T_FKT, E_FKT, *see Chapter 5.2, page 5-2*) or read (M_NR, Q_NR, S_NR, T_NR, E_NR, *see Chapter 5.4, page 5-4*) an auxiliary function, and, after they have been processed,
- acknowledge the auxiliary functions either individually (M_FKT_Q, Q_FKT_Q, S_FKT_Q, T_FKT_Q, E_FKT_Q, *see Chapter 5.3, page 5-3*), or acknowledge all pending auxiliary functions (M_ALL_Q, Q_ALL_Q, S_ALL_Q, T_ALL_Q, E_ALL_Q, *see Chapter 5.5, page 5-6*).

Task Using the 'M_ALL', 'Q_ALL', 'S_ALL', 'T_ALL', 'E_ALL' standard functions, it can be inquired according to the external circuitry whether the NC has output new M, Q, S, T, or E functions (and in which M function groups and/or for which spindle they have been transferred).


Circuitry



Deviations	Q_ALL	The Q_NR standard function does not possess a GROUP input.
	S_ALL	Instead of the GROUP input, the S_NR standard function has the SPINDLE input (spindle number 1 through 3 of the INT type).
	T_ALL	The T_NR standard function does not possess a GROUP input.
	E_ALL	The E_NR standard function does not possess a GROUP input.
Signals	ACTIVE	0: Inquiry of M function changes is not active 1: Inquiry of M function changes is active
	PROC	Process number (0 through 6)
	GROUP	M function group number (0 through 16) 0: Inquiry whether or not the NC has output an M function in one of the function groups 1 through 16. 1 through 16: Inquiry whether or not the NC has output an M function in the related function group 1 through 16

Signals	ACTIVE	0:	Auxiliary function inquiry is not active.
		1:	Auxiliary function inquiry is active.
	PROC		Process number (0 through 6)
	NR		M function number
	Function	0:	The standard function is not active or the standard function is active result and the NC has not transferred the auxiliary function concerned.
		1:	The standard function is active and the NC has output the auxiliary function concerned.

Example A specific action is to be performed in the PLC user program when the NC outputs the 'M890' M function.



5.3 Direct Acknowledgement of an Auxiliary Function (Specifying a Number)

General All M and Q functions which the NC transfers to the PLC must be acknowledged in the PLC user program. Since the user is able to inquire them with an appended 'W', this must also be done if the NC outputs the M or Q function as a swift auxiliary function.

Merely swift S, T, or E functions can do without acknowledgement; the execution of these functions cannot be inquired from the user program.


The following standard functions are available for acknowledging the auxiliary functions which the user has initiated with the 'inquiring an auxiliary function' standard function:

- M_FKT_Q,
- Q_FKT_Q,
- S_FKT_Q
- T_FKT_Q and
- E_FKT_Q.

Task

The 'M_FKT_Q', 'Q_FKT_Q', 'S_FKT_Q', 'T_FKT_Q', 'E_FKT_Q' standard functions enable a specific M, Q, S, T, or E function to be acknowledged.

Circuitry



Deviations

- Q_FKT_Q The NR input is of the INT type and has a value range of 0 through 9999.
- S_FKT_Q The S_FKT standard function has an additional SPINDLE input (spindle number 1 through 3 of the INT type). The NR input is of the DINT type and has a value range of 0 through 99999
- T_FKT_Q The NR input is of the DINT type and has a value range of 0 through 9999999.
- E_FKT_Q The NR input is of the INT type and has a value range of 0 through 9.

Signals

- QUIT 0: no acknowledgement of the M function
1: the M function is acknowledged
- PROC Process number (0 through 6)
- NR M function number (0 through 999)
- Function result The acknowledgement is transferred to the NC.



⇒ From software version 5.16 onwards, the related auxiliary function inquiry 'M_FKT', 'Q_FKT', 'S_FKT', 'T_FKT' or 'E_FKT' may no longer be programmed when an 'M_FKT_Q', 'Q_FKT_Q', 'S_FKT_Q', 'T_FKT_Q' or 'E_FKT_Q' auxiliary function is acknowledged. An auxiliary function must always be acknowledged as long as the related external state exist.

5.4 Reading an Auxiliary Function Number

General


- The
- M_NR,
 - Q_NR,
 - S_NR,
 - T_NR and
 - E_NR

standard functions enable the auxiliary function numbers from the NC to be read in the PLC program. They are best utilized for inquiring a complete range, as it is usually required for the S values of spindles, for example (see the example below).

Task

The 'M_NR', 'Q_NR', 'S_NR', 'T_NR', 'E_NR' standard functions enable the function numbers (of each function group 1 through 16) to be read.

Circuitry



Deviations

	Q_NR	The Q_NR standard function does not possess a GROUP input. As a function result it supplies an INT value with a value range of -1 through 9999.
	S_NR	Instead of the GROUP input, the S_NR standard function possesses the SPINDLE input (spindle number 1 through 3 of the INT type). As a function result, S_NR supplies a DINT value of a value range of -1 through 99999.
	T_NR	The T_NR standard function does not possess a GROUP input. As a function result it supplies a DINT value with a value range of -1 through 9999999.
	E_NR	The E_NR standard function does not possess a GROUP input. As a function result it supplies a DINT value with a value range of -1 through 9.
Signals	READ	0: Reading M function number is not active 1: Reading M function number is active
	PROC	Process number (0 through 6)
	GROUP	M function group number 0: Reading the M function numbers that have not yet been acknowledged in one of the 16 M function groups (starting at group 1). 1 through 16: Reading the last M function number to have been output within the selected group 1 through 16.
Function result	GROUP=Ø	-1: No M function is active. 0 through 999: The last M function number to have been output that has not yet been acknowledged. The M function number of the lowest group is displayed if auxiliary functions are output at the same time.
	GROUP=1 through 16	-1: Since the controller has been switched on, an M function has not yet been output for the M function group concerned. 0 through 999: Last M function number to have been output. Even after acknowledgement, it remains pending up to the next auxiliary function output (in the group concerned). Thus, reading the M function number permits the state of the M function as it exists in the NC (as it is shown in the status display) to be inquired at any time.

Instruction:

- Within an PLC cycle, one M function number can be read in each group (GROUP=1 through 16).
- If the user applies '0' to the GROUP input, the 'M_NR' function only reports the next active M function after the previous M function has been acknowledged.

Example When the S function of spindle '1' moves in the range from 'S8000' through 'S16000', an action shall be initiated in the PLC user program.


5.5 Acknowledging an Auxiliary Function (Specifying the Group)

General The

- M_ALL_Q,
- Q_ALL_Q
- S_ALL_Q,
- T_ALL_Q and
- E_ALL_Q

standard functions enable an executed auxiliary function to be acknowledged.

Task The 'M_ALL_Q', 'Q_ALL_Q', 'S_ALL_Q', 'T_ALL_Q', 'E_ALL_Q' standard functions permit all pending functions to be acknowledged according to the circuitry.



Deviations

Q_ALL_Q	The Q_ALL_Q standard function does not possess a GROUP input.
S_ALL_Q	Instead of the GROUP input, the S_NR standard function possesses the SPINDLE input (spindle number 1 through 3 of the INT type).
T_ALL_Q	The T_NR standard function does not possess a GROUP input.
E_ALL_Q	The E_NR standard function does not possess a GROUP input.

Signals

QUIT	0: No acknowledgement of the M function 1: The auxiliary function is acknowledged
PROC	Process number (0 through 6)
GROUP	M function group number 0: Acknowledgement of all pending M functions in all M function groups. 1 through 16: Acknowledgement of the pending M function in the selected M function group 1 through 16.

Function result The acknowledgement is transferred to the NC.

5.6 Sequence of the M00, M01, M02, and M30 Function Output

M Functions M00 and M01

Sequence Irrespective of the programmed sequence in the NC block, the NC transfers the M functions M00 (unconditional stop) and M01 (conditional stop) to the PLC at the end of the movement. The NC stops NC block execution ($P_{xx}SRUN = 0$) as soon as the auxiliary function concerned has been acknowledged and the NC has processed the remainder of the block.

The NC continues program execution ($P_{xx}SRUN = 1$) upon the next forward or backward start ($P_{xx}CADV, P_{xx}CREV$).

After the NC block has been terminated, the programmed M00 or M01 function appears in the status display until the program is restarted.

Interface signals




Fig. 5-5: Interface signals for the transfer of the M00 and M01 auxiliary functions

Instruction: In the case of the M00 and M01 functions and with the HLT command, the NC does not set the 'Program halted' ($P_{xx}SSTOP$) status signal.

M Functions M02 and M30

Sequence Irrespective of the programmed sequence in the NC block, the NC transfers the M functions M02 and M30 to the PLC at the end of the movement. The NC terminates program execution and resets the program (PxxSACTIV = 0 and PxxSRUN = 0) as soon as the auxiliary function concerned has been acknowledged and the NC has processed the remainder of the block.

The NC restarts program execution upon the next forward or backward start (PxxCADV, PxxCREV).

After the NC program has been terminated, the programmed M30 or M02 function appears in the status display until the program is restarted.

Interface signals




Fig. 5-6: Interface signals for the transfer of the M02 and M30 auxiliary functions

6 Index

A		M	
A00.087.....	3-1	M Function Groups.....	3-3
A00.088.....	3-2	M Functions.....	2-1
A00.089.....	3-2	Groups.....	2-2
A00.090.....	3-2	Machine Parameters.....	3-1
Acknowledging an auxiliary function (specifying a group).....	5-7	Acknowledgement behaviour.....	3-1
Auxiliary functions.....	2-1	Options.....	3-1
		Output behaviour.....	3-1
B		N	
Bxx.046.....	3-2	Normal Auxiliary Functions....	4-1
Bxx.047.....	3-2	Acknowledgement 'at the end of the movement'....	4-2
D		Output and acknowl- edgement 'at the begin- ing of a movement'.....	4-1
Deviating M Function.....	3-2	Output and acknowl- edgement 'at the end of the movement'.....	4-1
Deviating Q Function.....	3-2	Output 'at the beginning of the movement'.....	4-2
Direct acknowledgement of an auxiliary function (specifying a number)....	5-3	Output at the beginning of the movement.....	4-2
Direct inquiry of an auxiliary function (specifying the number).....	5-2	Short motion blocks.....	4-2
E		Output and Acknowledgement Behaviour.....	4-1
E Function.....	2-4	P	
G		PLC User Programming.....	5-1
Global M Function Mode.....	3-1	Q	
Global Q Function Mode.....	3-2	Q Functions.....	2-3
I		R	
Inquiring a change in the auxiliary functions (with group specification.....	5-1	Reading an auxiliary function number.....	5-4
		Reducing matching time.....	1-1

S

S Function Mode 3-2
 S Functions 2-3
 Sequence of the M Functions
 M00 and M01 5-8
 Sequence of the M Functions
 M02 and M30..... 5-9
 Swift auxiliary function
 No Auxiliary Function
 Output 4-5
 Swift auxiliary functions..... 4-3
 Contouring mode..... 4-3

Inquiring Swift
 M Functions 4-4
 Inquiring Swift
 Q Functions 4-4
 Swift M and Q Function Output
 4-3
 Swift S, T and E Function
 Output..... 4-5

T

T Function 2-4
 T/E Function Mode 3-2
 Time-optimized processing
 of auxiliary functions 1-1

7 Table of Figure

Fig. 4-1: Input of auxiliary function 'at the beginning of the movement' and acknowledgement 'at the beginning of the movement'	4-1	Fig. 4-3: Auxiliary function output 'at the beginning of the movement' and acknowledgement 'at the end of the movement'.....	4-2
Fig. 4-2: Input of auxiliary function 'at the beginning of the movement' and acknowledgement 'at the beginning of the movement'	4-1	Fig. 4-4: Typical inquiry of swift M and Q functions	4-5
		Fig. 5-5: Interface signals for the transfer of the M00 and M01 auxiliary functions.....	5-8
		Fig. 5-6: Interface signals for the transfer of the M02 and M30 auxiliary functions.....	5-9

Customer Service

Germany

Vertriebsgebiet Mitte INDRAMAT GmbH D-97816 Lohr am Main Bgm.-Dr.-Nebel-Str. 2 Telefon: 09352/40-0 Telefax: 09352/40-4885	Vertriebsgebiet Ost INDRAMAT GmbH D-09120 Chemnitz Beckerstraße 31 Telefon: 0371/3555-0 Telefax: 0371/3555-230	Vertriebsgebiet West INDRAMAT GmbH D-40849 Ratingen Hansastraße 25 Telefon: 02102/4318-0 Telefax: 02102/41315	Vertriebsgebiet Nord INDRAMAT GmbH D-22085 Hamburg Fährhausstraße 11 Telefon: 040/227126-16 Telefax: 040/227126-15
Vertriebsgebiet Süd INDRAMAT GmbH D-80339 München Ridlerstraße 75 Telefon: 089/540138-30 Telefax: 089/540138-10	Vertriebsgebiet Südwest INDRAMAT GmbH D-71229 Leonberg Böblinger Straße 25 Telefon: 07152/972-6 Telefax: 07152/972-727		INDRAMAT Service-Hotline INDRAMAT GmbH Telefon: D-0172/660 040 6 -oder- Telefon: D-0171/333 882 6

Customer Service in Germany

Europe

Austria G.L.Rexroth Ges.m.b.H. Geschäftsbereich INDRAMAT A-1140 Wien Hägelegasse 3 Telefon: 1/9852540-400 Telefax: 1/9852540-93	Austria G.L.Rexroth Ges.m.b.H. Geschäftsbereich INDRAMAT A-4061 Pasching Randlstraße 14 Telefon: 07229/4401-36 Telefax: 07229/4401-80	Belgium Mannesmann Rexroth N.V.-S.A. Geschäftsbereich INDRAMAT B-1740 Ternat Industrielaan 8 Telefon: 02/5823180 Telefax: 02/5824310	Denmark BEC Elektronik AS DK-8900 Randers Zinkvej 6 Telefon: 086/447866 Telefax: 086/447160
England Mannesmann Rexroth Ltd. INDRAMAT Division Cirencester, Glos GL7 1YG 4 Esland Place, Love Lane Telefon: 01285/658671 Telefax: 01285/654991	Finnland Rexroth Mecman OY SF-01720 Vantaa Riihimiehentie 3 Telefon: 0/848511 Telefax: 0/846387	France Rexroth - Sigma S.A. Division INDRAMAT F-92632 Gennevilliers Cedex Parc des Barbanniers 4, Place du Village Telefon: 1/41475430 Telefax: 1/47946941	France Rexroth - Sigma S.A. Division INDRAMAT F-69634 Venissieux - Cx 91, Bd 1 Joliot Curie Telefon: 78785256 Telefax: 78785231
France Rexroth - Sigma S.A. Division INDRAMAT F-31100 Toulouse 270, Avenue de l'ardenne Telefon: 61499519 Telefax: 61310041	Italy Rexroth S.p.A. Divisione INDRAMAT I-20063 Cernusco S/N.MI Via G. Di Vittoria, 1 Telefon: 02/92365-270 Telefax: 02/92108069	Italy Rexroth S.p.A. Divisione INDRAMAT Via Borgomanero, 11 I-10145 Torino Telefon: 011/7712230 Telefax: 011/7710190	Netherlands Hydraudyne Hydrauliek B.V. Kruisbroeksestraat 1a P.O. Box 32 NL-5280 AA Boxtel Telefon: 04116/51951 Telefax: 04116/51483
Spain Rexroth S.A. Centro Industrial Santiago Obradors s/n E-08130 Santa Perpetua de Mogoda (Barcelona) Telefon: 03/718 68 51 Telex: 591 81 Telefax: 03/718 98 62	Spain Goimendi S.A. División Indramat Jolastokieta (Herrera) Apartado 11 37 San Sebastian, 20017 Telefon: 043/40 01 63 Telex: 361 72 Telefax: 043/39 93 95	Sweden AB Rexroth Mecman INDRAMAT Division Varuvägen 7 S-125 81 Stockholm Telefon: 08/727 92 00 Telefax: 08/64 73 277	Switzerland Rexroth SA Département INDRAMAT Chemin de l'Ecole 6 CH-1036 Sullens Telefon: 021/731 43 77 Telefax: 021/731 46 78
Switzerland Rexroth AG Geschäftsbereich INDRAMAT Gewerbestraße 3 CH-8500 Frauenfeld Telefon: 052/720 21 00 Telefax: 052/720 21 11	Russia Tschudnenko E.B. Arsenia 22 153000 Ivanovo Rußland Telefon: 093/22 39 633		

Customer Service in Europe

Outside of Europe

<p>Argentina</p> <p>Mannesmann Rexroth S.A.I.C. Division INDRAMAT Acassusso 48 41/7 1605 Munro (Buenos Aires) Argentina</p> <p>Telefon: 01/756 01 40 01/756 02 40 Telex: 262 66 rexro ar Telefax: 01/756 01 36</p>	<p>Argentina</p> <p>Nakase Asesoramiento Tecnico Diaz Velez 2929 1636 Olivos (Provincia de Buenos Aires) Argentina Argentina</p> <p>Telefon 01/790 52 30</p>	<p>Australia</p> <p>Australian Industrial Machinery Services Pty. Ltd. Unit 3/45 Horne ST Campbellfield VIC 2061 Australia</p> <p>Telefon: 03/93 59 0228 Telefax: 03/93 59 02886</p>	<p>Brazil</p> <p>Mannesmann Rexroth Automação Ltda. Divisão INDRAMAT Rua Georg Rexroth, 609 Vila Padre Anchieta BR-09.951-250 Diadema-SP Caixa Postal 377 BR-09.901-970 Diadema-SP</p> <p>Telefon: 011/745 90 65 011/745 90 70 Telefax: 011/745 90 50</p>
<p>Canada</p> <p>Basic Technologies Corporation Burlington Division 3426 Mainway Drive Burlington, Ontario Canada L7M 1A8</p> <p>Telefon: 905/335-55 11 Telefax: 905/335-41 84</p>	<p>China</p> <p>Rexroth (China) Ltd. Shanghai Office Room 206 Shanghai Intern. Trade Centre 2200 Yanan Xi Lu Shanghai 200335 P.R. China</p> <p>Telefon: 021/627 55 333 Telefax: 021/627 55 666</p>	<p>China</p> <p>Rexroth (China) Ltd. Shanghai Parts & Service Centre 199 Wu Cao Road, Hua Cao Minhang District Shanghai 201 103 P.R. China</p> <p>Telefon: 021/622 00 058 Telefax: 021/622 00 068</p>	<p>China</p> <p>Rexroth (China) Ltd. 1430 China World Trade Centre 1, Jianguomenwai Avenue Beijing 100004 P.R. China</p> <p>Telefon: 010/50 50 380 Telefax: 010/50 50 379</p>
<p>China</p> <p>Rexroth (China) Ltd. A-5F., 123 Lian Shan Street Sha He Kou District Dalian 116 023 P.R. China</p> <p>Telefon: 0411/46 78 930 Telefax: 0411/46 78 932</p>	<p>Honkong</p> <p>Rexroth (China) Ltd. 19 Cheung Shun Street 1st Floor, Cheung Sha Wan, Kowloon, Honkong</p> <p>Telefon: 741 13 51/-54 und 741 14 30 Telex: 3346 17 GL REX HX Telefax: 786 40 19 786 07 33</p>	<p>India</p> <p>Mannesmann Rexroth (India) Ltd. INDRAMAT Division Plot. 96, Phase III Peenya Industrial Area Bangalore - 560058</p> <p>Telefon: 80/839 21 01 80/839 73 74 Telex: 845 5028 RexB Telefax: 80/839 43 45</p>	<p>Japan</p> <p>Rexroth Co., Ltd. INDRAMAT Division I.R. Building Nakamachidai 4-26-44 Tsuzuki-ku, Yokohama 226 Japan</p> <p>Telefon: 045/942-72 10 Telefax: 045/942-03 41</p>
<p>Korea</p> <p>Rexroth-Seki Co Ltd. 1500-12 Da-Dae-Dong Saha-Gu, Pusan, 604-050</p> <p>Telefon: 051/264 90 01 Telefax: 051/264 90 10</p>	<p>Korea</p> <p>Seo Chang Corporation Ltd. Room 903, Jeail Building 44-35 Yoido-Dong Youngdeungpo-Ku Seoul, Korea</p> <p>Telefon: 02/780-82 07 -9 Telefax: 02/784-54 08</p>	<p>Mexico</p> <p>Motorización y Diseño de Controles, S.A. de C.V. Av. Dr. Gustavo Baz No. 288 Col. Parque Industrial la loma Apartado Postal No. 318 54060 Tlalnepantla Estado de Mexico</p> <p>Telefon: 5/397 86 44 Telefax: 5/398 98 88</p>	
<p>USA</p> <p>Rexroth Corporation INDRAMAT Division 5150 Prairie Stone Parkway Hoffman Estates, Illinois 60192</p> <p>Telefon: 847/645-36 00 Telefax: 857/645-62 01</p>	<p>USA</p> <p>Rexroth Corporation INDRAMAT Division 2110 Austin Avenue Rochester Hills, Michigan 48309</p> <p>Telefon: 810/853-82 90 Telefax: 810/853-82 90</p>		

Customer Service outside of Europe

